

25 SEPT 1963.

- SYSTEM III REPEAT SYSTEM III:
  - RECEIVER A NORMAL OPERATION.
- RECEIVER B INTERMITTENT KEY PULSE (04 OR 05 BOARD FAILURE)
- C. RECEIVER C - NORMAL OPERATION. IN SOME CASES NOT E: THE DIFFERENCE BETWEEN MAXIMUM AND MINIMUM RECEIVER SENSITIVITY IS TOO LARGE. 5 TO 7 DB SHOULD BE THE MAXIMUM DIFFERENCE IN THE RECEIVER SENSITIVITIES.
  - "B" UNIT: NORMAL OPERATION.

END OF MESSAGE